

Oil Field Environmental Incident Summary

Incident: 20150401161513 **Date/Time of Notice:** 04/01/2015 16:15

Responsible Party: SAMSON RESOURCES COMPANY

Well Operator: SAMSON RESOURCES COMPANY

Well Name: HANSON 30-163-98H

Field Name: AMBROSE

Well File #: 16549

Date Incident: 4/1/2015

Time Incident: 08:00

Facility ID Number:

County: DIVIDE

Twp: 163

Rng: 98

Sec: 30

Qtr:

Location Description:

Submitted By: Brad Rogers

Received By:

Contact Person: Jeff Proberts

2 W 2ND ST SAMSON PLAZA

TULSA, OK 74103-3101

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels			0	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/7/2016

Clean Up Concluded: 4/1/2015

Risk Evaluation:

None

Areal Extent:

180' x 60' of oil mist on top of grass

Potential Environmental Impacts:

Offsite grass impacted by oil mist will be clipped and bagged for disposal.

Action Taken or Planned:

Heater treater and well were shut in upon discovery of release. Grass affected by oil mist will be clipped and bagged for disposal.

Wastes Disposal Location: all waste will disposed of at 13 Mile Landfill.

Agencies Involved: 4.1.2015 - Notified Mark Binns by phone regarding spill.

Updates

Date: 4/1/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, was not contained and impacted grass off site according to the report. Followup is necessary.

Date: 4/27/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume: 3.00 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Inspected the site on April 23, 2015. Weather was rainy with wind out of the SE at 15-20 mph. The area of impact was east of the oil pad. Impacted about 160' by 60' of stubble field. The field had been mowed, and all impacted material had been removed.

A slough is located an additional 350 yards east of the impacted area of the field. At the time of the inspection, there was no visible sheen or oil on the vegetation or water in the area of the slough, indicating surface water was not impacted by the oil spray. Only the stubble field adjacent to the oil pad was impacted.

No further followup needed for this site.